

Track Monitoring Data Systems for Evaluation of Earthworks Instability

*Ian Payne – Senior Asset Engineer (Geotechnics)
Jonathan Garelick – Asset Engineer (Geotechnics)
Jason Lund - On Track Machine Engineer*

26th October 2017

Presentation is part of a more detailed paper skeleton

Title – Track Monitoring Data Systems for Evaluation of Earthworks Instability

1. Introduction

Purpose of the paper

Why important

What included and what not included

Digital age limits track walkouts but still need to visit sites r

2. Data Capture

Track recording train

Routeview

LADS Output

Omnicom

JBA Earthworks reports/Inclinometer data

BGS Database

Slope monitoring instrumentation

Google/BING Mapping

RINM Cross sections

OLE height/stagger

3. Track Behaviour

What does good track look like

Maintenance intervention types

Ballast properties and behaviour

Embankment fill properties and behaviour (Ash Fill/Clay fill etc)

Track zone of influence

4. Twist Faults/Cant deficiencies

(a) Track Related issues

- wet beds

-cyclic top on one rail

(b) Earthworks related issues

- Tree Desiccation cyclic top on one rail

- Slope instability

- Burrowing

5. Alignment Faults

(a) Track Related issues

- wet beds

(b) Earthworks related issues

- Slope instability

6. Maintenance Interventions/Trend analysis

(a) Track Related issues

- wet beds

(b) Earthworks related issues

- Slope instability

- Desiccation (trend analysis)

7. Dip Angle

(a) Track Related issues

- Jointed track on poor foundation

(b) Earthworks related issues

- Slope instability

- Bridge run-on/off

8. Rolling SD (Rolling eights/static eighths)

(a) Track Related issues

- Ballast attrition

(b) Earthworks related issues

- Slope instability

9. Ground Probing Radar

(a) Track Related issues

- Contaminated ballast

(b) Earthworks related issues

- Slope instability

- Pockets of water

10. Future Innovations

Satellite monitoring

Vibration Detection Units

Argo

11. Conclusions/Summary

Lessons learnt

Further work

Need to differentiate between Earthworks Failures and other Track Failures (cyclic top, poor ballast, switches and crossings, track joints etc)

ISSUES DISCUSSED IN PRESENTATION

[Introductions](#)

[Anglia Earthworks](#)

[Track Recording Data \(LADS\)](#)

[Earthworks and Drainage Issues](#)

[Deep seated slope instability](#)

[Desiccation](#)

[Structures Run-on/off](#)

[Wet Beds](#)

[Other Track Issues](#)



[Maintenance effectiveness](#)

[Poor ballast condition](#)

Some Background Information Geology/Embankments/Rainfall/Drainage



Large post construction collapse settlement following rainfall infiltration.
Readily available locomotive ash and track ballast reinstated embankments.



Range of Typical Anglia Earthworks Failures



Deep seated London Clay embankment instability
Chelmsford 2009



London Clay cutting slope failures
Walthamstow Central 2009




Perched Water table instability
(Tills over Clays) Brantham Hall 2014



Glacial Till/Crag Washouts
Wymondham 2017



Ash degradation /instability
Nags Head Lane 2016



Storm Surge track and embankment washouts
Haddiscoe 2014



Chalk Slope instability
Coalpit Cutting 2013



Peat Wastage /Subsidence
Thrandeston Bog 2008



Badger burrowing subsidence
Fordham 2016



Rabbit burrowing subsidence
Pesthouse Lane 2015



Clay Desiccation Track instability
Great Bentley 2009




Ash Fires
Jacques Hall 1985

West Horndon to Dunton - FSS2 19m 35ch to 20m 55ch

Typical of issues on many embankments in Anglia



- Slope Slip Surface Instability
- Soil Creep
- Vermin Burrowing
- Tree Root Desiccation
- Ash Degradation



- Thick Ballast
- Structures Run-on/Run-off
- Poor Toe Drainage
- Locally Prolific Hydrophilic Horsetail
- Wet Beds
- Inadequate Cess Walkways
- Historic Patchwork of Treatments





What Is LADS


Linear Asset Decision Support (LADS) is a decision support tool designed to improve how you carry out Track, Earthworks and OLE maintenance inclusive of renewals . It is an integrated dashboard view of track asset information and is a key enabler in better understanding:-

- Rates of asset degradation
- Different track fault types
- Determining the effectiveness of renewals and maintenance interventions,
- Predicting work volumes and output
- Targeted systems intervention

It allow greater validation of the proposed interventions and is part of a wider Asset Management toolkit




Data Presented by LADS



<i>Data Source</i>	<i>Asset Information</i>	<i>Refresh *</i>	<i>History/Retention</i>
ACTRAFF:	Traffic (EMGTPA)	Periodically	12 months history
CARRS	Structures	One Off	Current record
Ellipse	S&C, Level Crossings, On track Assets, Drainage, Workbank	Weekly Monthly Daily	Current record
GEOGIS	Track Asset Register	Weekly	Current record
Radargrams & Ballast Fouling Index	Ground Penetrating Radar (GPR)	Monthly	Current record
JBA	Earthworks	One Off	Current record
RDMS	Rail Defects, Rail Breaks, Rail Suspects, Rail RCF	Daily	Current record (3 yrs history)
GMS	Network Model	Monthly	Current record
TICLED	Tight Clearances	One Off	Current record
CDMS/TGR:	Track Geometry	Daily	3 yrs history
TRS:	Renewals	Weekly	Current record (3 yrs history)


What Good LADS Track Data Looks Like





What Bad LADS Track Data Looks Like



Ashdon Way Basildon – LADS data with Deeper 400Hz GPR




Ashdon Way Basildon – Deep Seated Progressive Embankment Failure (FSS2 23m 60ch to 24m 10ch)






Tostock Embankment – Deep Seated Progressive Failure


(CCH 34m 65ch)




- Early identification of problem area extents
- Both GPR and twist faults show similar extents
- Identified progressive deterioration
- Targeting site investigation and embankment monitoring locations



Wrabness Embankment – Deep Seated Progressive Failure (MAH 65m 60ch to 70ch)




Sleeper Ends Exposed - Twist Fault




Long Dip in track – Alignment Fault

Wrabness LADS track data 65M TO 66M – Up and Down Comparison



DOWN Side



UP Side

Blountswood Road SSV 34m 05ch to 65ch



Slope Slip Surface Instability

Soil Creep

Vermin Burrowing

Ash Degradation

Poor Toe Drainage

Leaning OLE Mast

Thick Ballast

Locally Prolific Hydrophilic Horsetail

Leaning trees


Inadequate Cess Walkways

Historic Patchwork of Treatments




Blountswood Road SSV 34m 05ch to 65ch Up and Down LADS Comparison

Down





Up




Blountswood Road SSV 34m 05ch to 65ch Down LADS data

GPR features at 25ch and 61ch



SSV 34ml 25.25ch to 34ml 25.75ch Down embankment shoulder drops and walkway restrained, but 3.5m cress, track good although recently tamped. Cress walkway in poor condition between 34ml 59.5ch and 34ml 65.75ch Down, track good but recently tamped. From 34ml 60.25ch to 34ml 63.5ch cress and walkway drops with increased ballast thickness, there is also Horsetail in walkway. There is a gabion toe berm between 34ml 60.75ch and 34ml 61.75ch



TWN 68m to 69m - LADS Up and Down (Single track) Problem 68m 45ch




Ulemans Farm WIS 38 miles 1100yds - Embankment instability





Ulemans Farm WIS 38 miles 1015yds to 1120yds - Embankment instability



Typical Anglia Embankment/Structure Run-on/Run-off Differential Settlements



Manea Viaduct Approach Embankments EMP 78m (east) to 79m (west) - LADS Down



Local Twist Faults on Peat Fens due to Trees

(ETN 72m 0880yds to 72m 1650yds Up)



Plate-6a-72m-1020yds-Up-to-0940yds



Plate-6b-72m-0940yds-Up



Plate-6c-72m-0908yds-Slack-and-Slew



Plate-6d-Willow-tree



Plate-6e-Routeview-of-Willow-tree



Plate-6f-72m-0880yds-Slack-and-Slew




Plate 5c 72m 1150yds Up from 1100yds





Plate 5d 72m 1150yds Up Willow

LADS Summaries ETN 72m 0800yds to 72m 1650yds Up




Maintenance effectiveness on Fens (EMP 74m 0550yds Up)

Stoneblowing more effective than Tamping




Clay Embankment Desiccation



BRE 412 "Desiccation in Clay Soils" - Desiccation in clay soils can result in shrinkage of the soil and subsidence of the ground; this may lead to damage to buildings. As the soil re-hydrates, it can swell, resulting in ground heave; this may also cause damage to buildings


Harold Wood Slope inclinometer boreholes

Seasonal cyclic and progressive movements



Chatteden London Clay BRE Settlement rods



Seasonal cyclic and progressive movements showing effects of trees and grass



Nearby tree shrinkage potential on shrinkable clay



Grass shrinkage potential on shrinkable clay

Wrabness Desiccation Rough Ride 65milesM 1317yds Down 28.09.17




Desiccation related track deterioration

Good Track Geometry on London Clay Soils FSS2 and TLL




TAH2 8m 1270yds to 1340yds Down Wet Beds


I-O 0153448.51 57422901 -> TAH2-8M+1339.7 I-O 0153302.51 57422681 0.4
15 Feb 2017 10:28:17



TAH2 8m 1270yds to 1340yds Down Wet Beds



ELR TAH2 8m 1381yds ±0
 Geo 51°34'26" 0°0'54"
 XYZ 537655 187982 16



Conclusions

1. Track monitoring data is a useful tool in the assessment of certain types of earthworks failure
2. Anglia Route are looking to undertake a wider Route review of such track monitoring data
3. Track monitoring data is a complimentary tool to supplement other existing earthworks assessment tools
4. Sharing case history data will hopefully assist in the more widespread use of such track monitoring data
5. Production of a more detailed user manual would further assist in the understanding of LADS
6. Network Rail are embarking centrally on a more detailed review of the benefits of using track monitoring data

The End

Track Monitoring Data Systems for Evaluation of Earthworks Instability

*Ian Payne – Senior Asset Engineer (Geotechnics)
Jonathan Garelick – Asset Engineer (Geotechnics)
Jason Lund - On Track Machine Engineer*

26th October 2017